



Guy Janssen, Key23D

Elst Gld,
17 augustus 2014

Settings: 0,1 layer, first layer 0,2.

Problem at layer 1091 at the top of the opening on the side; it jumps a bit outward.





This is a picture of the case of day 4!!

